


BLIP Status

- **Safety** – none
 - Sampling BLIP water Operator was contaminated.
 - Investigation will be initiated
- **Production**
 - Target to be processed next week
 - Target received less current expect lower yield
 - Total integrated - 30706.00 uAhr
 - Time: 264.47 (11.02 days) usually
 - Average Current - 116.11 uA
- **Maintenance**
- **Research/Other**
 - Sc-44 production test – 1 hr irradiation - scheduled for this week.

BLIP Performance, 2011 – 2015



Average Current for 2015 - New Integrator

